		residential areas			de la constante
6. Landslide/ erosion of exposed road sides resulting in sedimentation of waterways	[] The road will traverse a hilly area necessitating deep cuts on hillysides, particularly between station 7+920 – 7+980 sta. 9+450-9+500; sta. 9+590-9+620 [] The cut slopes will be hard materials that would resist erosion [] The road passes through a relatively benign terrain, cuts will be minimal [] The rehabilitation work does not involve additional road cuts	[] Include drainage canal through rip-rap station 7+920-7+980; sta. 9+450-9+500; sta. 9+590-9+620	During Constru ction	Compliance to the ESMP	BUILD HEAD and CONT RACT OR
7. Inadequate drainage resulting in flooding or ponding	[] The road will block runoff, resulting in flooding on one side of the road during rainy days. [] Drainage issues unlikely	[] Installation of cross drain between station 7+920-7+980; sta. 9+450-9+500; sta. 9+590-9+620	During Constru ction	DED	HEAD and CONT RACT OR
8. Local employment	[] Construction will provide local employment opportunities	[] Hiring priority shall be given to qualified local residents; Implement RI Manual on local hiring	During Constru ction	Contract	CONT RACT OR
9. Traffic Congestions generate by heavy equipment and transporting trucks during PCCP	[] Construction Management on materials and equipment	[] Establishment of Batching Plant [] Established proper signage and warnings on lane for concreting and provide detour for a passage lane [] Confine area intended for excavation [] Provision of adequate space for materials and equipment [] Provision of	During Constru ction	Contract	CONT RACT OR
9. Safety of School Children		adequate nets for falling debris at the batching plant [] Establishment of signage and warning signs in school sites	During Constru ction	Compliance the ESMP	CONT RACT OR